Work Order (Bid Form)

WODK	ADDED	INICODIA	TION
WURN	UKUEK	INFORMA	A I IUN

Work Order Name: WO/15015SE1043/2 Work Order Type: Weatherization Audit Name: 1043 Audit

CLIENT INFORMATION

Client Name: 1043 Address:

Client ID: 15015SE1043

Alt. Client ID: Bledsoe

CLIENT CONTACT INFORMATION

1043 Applicant/Person of SITE BUILT

Record

<u>AGENCY INFORMATION</u>

Agency Phone: (423) 949-2191 **Agency:** Southeast Tennessee Human Resource Agency

Address: 312 Resource Rd. Fax: (423) 949-4023

> Dunlap, TN 37327 Email Address: aramsey@sethra.us

Agency Contact: Quarles, Alex Work Phone:

Cell Phone: (423) 903-3286

Email Address:

Company Name & License Number:	
• •	

Contractor's Signature:

COMMENT

Contractor to verify all measurements. Lead Safety for EPA-RRP Compliance.

Client Name: 1043 Client ID: 15015SE1043 Alt. Client ID: Bledsoe

Work Order (Bid Form) Work Order Name: WO/15015SE1043/2 **DOE** Weatherization Assistant Version 8.6.0

Report Run On: 5/11/2010

Measures

Measure 1 Infiltration Redctn			Components H1					Inspected		
Comment Weatherstrip 2 exterior doors.			Estimated				 Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
10	Miscellaneous Su	Infiltration Reduction	Each	1						
c	Other Detail									
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									
	Measure 2 DWH	l Pipe Insulation			Componen	ts			Inspected	
C	omment	•			-					
					Estimated	·		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	DHW Pipe Insulation	Each	1						
		Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.								
2	Labor	DHW Pipe Insulation	Each	1						
3	Other	DHW Pipe Insulation	Each	1						
C	Other Detail									
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									

Page 2 of 4

	Measure 3 DWH	Tank Insulation			Componer	nts		ı	Inspected
C	omment								
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Tank Insulation	Each	1					
3	Other	DHW Tank Insulation	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Report Run On: 5/11/2010

Measure 4 PressureRelief Piping No	eeded		Componen	ts			Inspected
Comment							
			Estimated			Actual	
# Material / Labor Description / Comment	t Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Pressure relief piping	Each	1					
Water heater must have a copper or CPVC piper installed on pressure relief valve that should terminate through the floor. If this is not possible pipe can be rathrough the wall and terminated within six inches of the ground. more than two elbows may be used.	e I an						
2 Labor Labor	Each	1					
Other Detail							
		Measur	e Sub Total:			Sub Total:	
Field Notes:							
	Work Or	der Gra	nd Total:		Gran	d Total:	

Report Run On: 5/11/2010